



A Legal Survey by William P. Pase 3-23-1857 called witnesses: 10" oak N 16 and 12" oak S 20 E 40 links per Lawrence Township Legal Survey Book pg. 21. Miller 5-22-75 called a PK nail 2" down. Gries 6-16-88 called the same. Kiste 5-4-94 called an angle iron found 9" down. Part of a broken-off concrete fence post was found 18" down. Harrison was set. Re-tied 7-8-99 by Kiste.

16.9	-	r	- 8	4	15	n	=
H		h	4	1	~	и	٦.
4.4	•	v	11.0	-	_	v	~

REF.	DISTANCE	DESCRIPTION			
1,	18.50′	Cut 'x' N corner storm inlet			
2.	17.00'	Road nail S PwP no# 18"up			
3.	89.80′	NW corner of frame address: 6510			
4.	163.88′	Top nut of fire hydrant			
5.	77.70′	NE corner address: #5202			
6.	34.59'	PK nail w/washer N PwP#572-348 10"up			
7.	31.18′	Cut 'x' S corner of storm inlet			
8.	119.49'	Cut 'x' S-rim of sewer manhole			